



7

Scheibe entfernen
Fjern skive
Avlägsna skiva
Fjern skiven
Poista levy

min. \varnothing 18 mm

max. 10 Nm

Dichtheit nach einem Spülgang prüfen
Kontroller tæthed efter en vask
Kontrollera tætheten efter en diskning
Kontroller tettheten etter en vaskeomgang
Tarkista tiiviy pesun jälkeen

GB → → → → GB

\varnothing 38 mm

max. 1.1 m
min. 280 mm

26.4 mm 20.9 mm
(G 3/4") (G 1/2")

min. 10 mm

0.05 - 1 MPa
(0.5 - 10 bar)
max. 60°C

10

11

12

